READ ALL INSTRUCTIONS BEFORE BEGINNING INSTALLATION

INSTALLATION INSTRUCTIONS

- 1- REMOVE THE EXISTING SUN VISOR AND KEEP THE FASTENING HARDWARE.
- 2- INSTALL THE BRACKETS ONTO THE EXISTING HOLES.
- 3- USE THE FASTENING HARDWARE FROM PREVIOUS VISOR.
- 4- FASTEN CENTRAL SUPPORT LEG AS ILLUSTRATED.
- 5- TEMPORARILY INSTALL THE SUN VISOR ON THE BRACKETS AS ILLUSTRATED
- 6- FASTEN EACH SIDE OF SUN VISOR TO EXISTING HOLE USING **EXISTING HARDWARE.**
- 7- MARK EXTRA SIDE HOLES OF SUN VISOR.
- 8- MARK THE CENTRAL SUPPORT LEG HOLE ONTO THE CENTRAL GASKET ON WINDSHIELD. NOTE 8


ATTENTION REMOVE SUN VISOR TO PREVENT DAMAGE


- 9- DRILL THE CENTRAL SUPPORT LEG HOLE AS MARKED AT 7/32" (.21875") DIA.
- 10- DRILL THE SIDE HOLES AS MARKED AT 1/2" DIA. 11- INSERT THE WELL NUTS IN THE HOLES.
- 12- SUN VISOR WITHOUT LIGHTS; SKIP TO STEP 17.
- 13- INSTALL THE LIGHTS ON SUN VISOR
- 14- CONNECT THE LIGHTS AND DIRECT WIRE TOWARDS CENTER.
- 15- INSTALL AND CONNECT THE CENTRAL LIGHT TO THE OTHERS.

CAUTION

IT IS THE RESPONSIBILITY OF THE INSTALLER TO PLAN A HEAD THE ADEQUATE ELECTRICAL CONNECTION ACCORDING TO THE STANDARDS OF THE TRUCK MANUFACTURER AND DOT REGISTRATION.

- 17- REINSTALL THE SUN VISOR ON THE CAB.
- 18- IF SUN VISOR HAS LIGHT, CONNECT LIGHTS HARNESS TO THE TRUCK.
- 19- TIGHTEN ALL BOLTS AND SCREWS.





TRUX ACCESSORIES

TITLE:


NOTE 8

CENTRAL

SUN VISOR WESTERN STAR

CONSTELLATION GANGSTER SERIES 1998 & UP

TSUN-W1				
	NAME	DATE	REV	DATE
DRAWN BY	P.W.	22-10-2008	PH1	1-
SCALE: 1:1		WEIGHT: LBS		SHEET: 1 OF 1



TRUSS PHILIPS #10-32NFX1 3/4"S

NYLON LOCK NUT #10-32NF SS

13

14

15

 NAME
 DATE
 REV
 DATE

 DRAWN BY
 P.W.
 22-10-2008
 PH 1

 SCALE: 1:1
 WEIGHT: LBS
 SHEET: 1 OF 1